

## References

**Cruz, R. (2012).** Assessing the Health of Streams in Agricultural Landscapes: How Land Management Changes Impact Water Quality. R. Cruse, editor. A technical report by the Council on Agricultural Science and Technology (CAST): Ames, Iowa.


**Schilling, K. E., & Libra, R. D. (2003).** INCREASED BASEFLOW IN IOWA OVER THE SECOND HALF OF THE 20TH CENTURY<sup>1</sup>. JAWRA Journal of the American Water Resources Association, 39(4), 851-860. Smith

**Smith, E. A. (2012).** Spatial and temporal variability of preferential flow in a subsurface-drained landscape in north-central Iowa. University of Minnesota.

**Wagner, M.M. 2011.** Ames Stream Assessment 2011. Ames, Iowa. Final Report, February 6, 2012.

**Wagner, M. M., & Gobster, P. H. (2007).** Interpreting landscape change: Measured biophysical change and surrounding social context. Landscape and Urban Planning, 81(1), 67-80. Wendt 2007

**Wendt, A. A. (2007).** Watershed Planning in Central Iowa: An Integrated Assessment of the Squaw Creek Watershed for Prioritization of Conservation Practice Establishment. ProQuest.



## Hydrology

- Decreased grassland
- Changes to riparian vegetation cover
- Drainage
- General increase in annual precip
- Increase in # of rainfall events exceeding 2 inches in 24 hours




## Wagner 2011

- Quantitative
- Lower watershed focus (Ames)
- 41 miles of perennial stream

## Wagner 2011

- **Bank Erosion**
  - Estimate of sediment loading
  - 25-30k tons of gross sediment
- **2006 to 2011 Comparison**
  - aside from 2010 flood little overall change in channel morphology





## Wagner 2011


- **Bank Erosion**
  - Estimate of sediment loading
  - 25-30k tons of gross sediment
- **2006 to 2011 Comparison**
  - aside from 2010 flood little overall change in channel morphology



Survey Parameter	Categories				
<b>Substrate</b>	<b>Boulder</b>	<b>Cobble</b>	<b>Gravel</b>	<b>Sand</b>	<b>Silt/Mud</b>
# of surveys : 340	17 5.0%	31 9.1%	94 27.6%	156 45.9%	42 12.4%
<b>Bank Stability</b>	<b>Artificially Stable</b>	<b>Stable</b>	<b>Mod. Stable</b>	<b>Mod. Unstable</b>	<b>Unstable</b>
# of surveys : 346	4 1.2%	41 11.8%	168 48.6%	103 29.8%	30 8.7%
<b>% of Bank Bare</b>	<b>0-20%</b>	<b>20-40%</b>	<b>40-60%</b>	<b>60-80%</b>	<b>80-100%</b>
# of surveys : 346	150 43.4%	106 30.6%	47 13.6%	28 8.1%	15 4.3%
<b>Bank Height</b>	<b>0-3'</b>	<b>3-6'</b>	<b>6-10'</b>	<b>10-15'</b>	<b>&gt;15'</b>
# of surveys : 346	30 8.7%	256 74.0%	50 14.5%	5 1.4%	5 1.4%
<b>Livestock Access</b>	<b>Yes</b>	<b>No</b>			
# of surveys : 346	77 22.3%	269 77.7%			

## Wendt

- Entire watershed
  - Representative reaches
  - Excludes ditches
- Qualitative stream assessment
- Field erosion & buffer conditions
- Sediment delivery “hot spots”



## Wendt

- Entire watershed
  - Representative reaches
  - Excludes ditches
- Qualitative stream assessment
- Field erosion & buffer conditions
- Sediment delivery “hot spots”



## Reaction

- Unclear how much sediment has been transported versus contained
- Unclear % of field and bank
- Impacts of ditch maintenance
- Contradiction of two primary studies
- Underestimate of field erosion (gully)